



## **2021 REV BOX BULLETIN (5/24/21)**

*Please note the added verbiage to rule 2 under **ENGINES** that is in red and underlined:*

Effective June 5, 2021, MSD RPM (rev) limiter box part #8727CT and connector lead must be mounted on the left side of the engine compartment firewall; display screen must be in clear view without removing hood.